

Case 277 : Narrative

Case Vehicle (A): 2000 Honda	Vehicle (B): 2000 Subaru
Type: CRV, 4-door SUV	Type: Legacy Outback, 4-door station wagon
Driver: 53-year-old female	Driver: 35-year-old male
CDC: 12-FREE-3	CDC: 99-0000-0

SITUATION

[1](#) Case vehicle (A) was traveling east in the left-turn lane of a five-lane asphalt roadway, and was approaching a three-leg intersection with a two-lane roadway. [2](#) Vehicle (B) was traveling north in the northbound lane of the intersecting two-lane roadway. It was daylight and the roadway was dry and in good condition. As case vehicle (A) approached the intersection, the driver of vehicle (B) pulled out to make a left turn, and crossed into the path case vehicle (A). The right front of case vehicle (A) struck the left front of vehicle (B). The driver of case vehicle (A) was transported to a local level-one trauma center but was not admitted. The driver of case vehicle (A) had been drinking alcohol and had a BAC of 0.09%. The driver, right-front, and right-rear passengers of vehicle (B) were not transported to a medical facility. Both vehicles were towed due to damage.

GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

[3](#) The direct-damage length along the front of case vehicle (A) was 32 cm, resulting in 24% vehicle overlap (VOL). It began at the right-front bumper corner and ended below the center of the right headlight assembly. The maximum crush at the bumper level was 26 cm and occurred at the right-front bumper corner. The left wheelbase was reduced 7 cm, and the right wheelbase was reduced 26 cm.

Using the ROLDMISS option of the WinSMASH accident-reconstruction program and [4](#) [5](#) [6](#) c-values for case vehicle (A), the following impact severities were calculated for the frontal impact to case vehicle (A) and the side impact for vehicle (B):

		Calculated Velocity Change - kph (mph)		
Vehicle	Variable	Total	Longitudinal	Latitudinal
Case Vehicle (A)	delta V	18 (11)	-18 (-11)	-3 (-2)
Vehicle (B)	delta V	17 (11)	-3 (-2)	17 (11)

DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

Exterior

[7](#) Damage to the front of the vehicle includes crush to the bumper, displacement of the bumper fascia, and damage to right headlight assembly. The hood latch was not damaged and did not release. The rear edge of the hood was not elevated and did not contact the windshield.

[8](#) There was crush to the front portion of the right fender and induced damage to the rear portion that extended rearward to the lower A-pillar. The right-front tire was completely deflated and the wheel was displaced rearward, resulting in a 26-cm reduction of the right wheelbase. No other damage was noted to the right side of the vehicle.

[9](#) [10](#) No damage was noted to the rear of the vehicle or to the left side of the vehicle.

Interior

[11](#) [12](#) [13](#) [14](#) [15](#) This vehicle was equipped with both steering-wheel and passenger frontal-impact airbags, which deployed during the frontal impact. No damage was noted to the airbag skins or [16](#) [17](#) [18](#) [19](#) [20](#) [21](#) to the module doors/flaps. [22](#) There was no apparent deformation of the steering-wheel rim or spokes.

[23](#) [24](#) [25](#) [26](#) [27](#) There was no damage to the windshield header, the roof structure, the roof siderails, or the roof-mounted console. The upper-center portion of the windshield was cracked and had an oil deposit from occupant contact. The rearview mirror was knocked off of its mount but was not found in the vehicle. [28](#) There was no damage to the driver sunvisor. [29](#) [30](#) A cloth transfer was noted on the far left side of the driver knee bolster. [31](#) [32](#) A scuff mark and a dent were noted on the right side of the driver knee bolster, just below the ignition switch. The driver seat was not damaged and there was no apparent seat rotation. [33](#) The front seatbelt pre-tensioners had fired and locked the shoulder belts in the fully retracted position. The seat-adjuster mechanism was not damaged, and the driver seat was in the full-rearward position. No intrusions were noted.

OCCUPANT INJURIES AND KINEMATICS

The 5-ft, 6-in, 135-lb, 53-year-old female driver was **not** wearing the available three-point belt, as evidenced by the shoulder belt being locked in the fully retracted position, and [34](#) the steering-wheel frontal-impact airbag deployed. Her seat was reportedly at a mid-track position, and she had positioned her hands at the 10 and 2 o'clock positions on the steering wheel rim. [35](#) During the impact, she moved forward into the airbag. Her left knee struck the far left side of the driver knee bolster [29](#) [30](#) and her right knee struck the right knee bolster just above the accelerator pedal [31](#) [32](#) , but she did not sustain any knee, pelvic, or lower extremity injuries. She sustained an abrasion and contusion to the right side of the forehead at the hairline, probably due to contact by the airbag, but possibly from contact with the windshield. She also sustained a contusion to the left eye, probably from contact by the airbag or from the airbag flinging her right forearm and hand into her face, but possibly from contact with the windshield. She sustained an abrasion and contusion to the right distal medial forearm, probably from contact by the airbag. [36](#) [37](#) She sustained a contusion to the right elbow, probably from contact by the airbag but possibly from contact with the windshield. She sustained neck and thoracic spine muscle strain, probably from impact forces.

The following table and [38](#) attached drawing summarize the injuries sustained by the driver.

Occupant: Driver	Age: 53 years	Gender: Female		
Restraints: 3-point belt <i>not</i> worn; airbag deployed	Stature: 168 cm (5 ft, 6 in)	Mass: 61 kg (135 lb)		
Injury Description	A.I.S.	Injury Source		
		Definite	Probable	Possible
—	—	—	—	—
Contusion, right side of forehead at hairline	1	—	Airbag	Windshield
Abrasion, right side of forehead at hairline	1	—	Airbag	Windshield
Muscle strain, neck	1	—	Impact forces	—
Muscle strain, thoracic spine	1	—	Impact forces	—
Contusion, distal medial right forearm	1	—	Airbag	—
Abrasion, distal medial right forearm	1	—	Airbag	—
Contusion, right elbow	1	—	Airbag	Windshield
Contusion, left eye	1	—	Airbag, right forearm/hand (airbag fling)	Windshield
Maximum A.I.S. Level	1	—	—	—
Injury Severity Score	3	—	—	—

CASE NO.: 277-01

CASE VEHICLE: 2000 Honda


TYPE: CRV, 4-door SUV

OCCUPANT: (Driver): 53-year-old female

STATURE: 168 cm (5 ft, 6 in) MASS: 61 kg (135 lb)

RESTRAINTS: 3-point belt not worn; airbag deployed

SEVERITY: MAIS - 1 : ISS - 3



Case No.: 277-01

Veh. (A): 2000 Honda

Type: CRV, 4-door SUV

Driver: 53-year-old female

Veh. (B): 2000 Subaru Legacy Outback, 4-door station wagon

Light Conditions: Daylight


Weather: Clear

Road Surface: Dry

Road Construction: Asphalt



Speed limit 64 kph (40 mph)



Vehicle Report

General

Conditions

Variable Number and Name	Code Value	Code Description	Other Options
V206 — Urban/Rural Area	1	Urban	more
V207 — Limited Access Highway	0	No	more
V208 — Road Total Lanes	4	4 lanes or more	more
V209 — Intersecting Road Total Lanes	2	2 lanes	more
V210 — Road Surface Type	1	Asphalt	more
V211 — Road Defects	0	No	more
V212 — Construction Zone	0	No	more
V213 — Road Alignment Vertical Plane	1	Level	more
V214 — Road Alignment Horizontal Plane	1	Straight	more
V215 — Surface Covering	10	Dry	more
V216 — Visibility Limitation	0	None	more
V217 — Visibility Obstruction	0	None	more
V218 — Speed Limit	3	61-70 km/h .. 40 mph	more
V219 — Precipitation Type	0	None	more
V220 — Precipitation Rate	8	Not applicable	more
V221 — Temperature	9	Unknown	more
V222 — Crosswind	9	Unknown	more
V223 — Light Conditions	1	Daylight	more
V224 — Mechanical Malfunction Mention	0	No	more
V225 — Case Vehicle and Object	0	No	more
V226 — Case Vehicle Rollover	0	No	more

V227 — Case Vehicle Ran Off Roadway	0	No	more
V228 — Moving Case Vehicle/Contacted Moving Vehicle	1	Yes	more
V229 — Case Vehicle/Contacted Stopped Vehicle	0	No	more
V230 — Stopped Case Vehicle/Contactd Vehicle	0	No	more
V231 — Total Vehicles Hit By Case Vehicle	1	1 vehicle	more
V232 — Any Fire in Crash	0	No	more
V233 — Max Police Severity-PAR	2	B - Non-Incapacitating Injury	more
V234 — Driver Alcohol Involvement	1	Had been drinking	more
V235 — Driver Alcohol BAC	09	—	—
V236 — Driver Impairment Mention	1	Yes	more
V237 — Driven/Towed From Scene	2	Towed Due to Damage	more

Other Vehicle

Variable Number and Name	Code Value	Code Description	Other Options
V301 — Other Vehicle VIN	4S3BH6652Y76	—	—
V302 — Other Vehicle Manufacturer/Body Code	88227	—	—
V303 — Other Vehicle Manufacturer	882	Fugi Heavy Industries (Subaru)	more
V304 — Other Vehicle Body Code	27	Compact 100-104.9 in. wb.	more
V305 — Other Vehicle Make/Model	2626	Legacy	more
V306 — Other Vehicle Model Year	2000	—	—
V307 — Other Vehicle Mass	001590 kg	—	—
V308 — Other Vehicle Number	0	No separate report	more
V309 — Other Vehicle Number of Occupants	03	—	—
V310 — Other Vehicle Traveling Speed	999	Unknown	more
V311 — Highest Police Injury Severity	1	C - Possible Injury	more
V312 — Other Vehicle Type	27	Compact 100-104.9 in. wb.	more
V313 — Other Vehicle Wheelbase (cm)	265 cm	—	—
V314 — Average Track Width	147 cm	—	—
V315 — Overall Length	476 cm	—	—
V316 — Overall Width (OAW)	175 cm	—	—
V317 — Front Overhang (FOH)	099 cm	—	—
V318 — Rear Overhang (ROH)	112 cm	—	—
V319 — Undeformed End Width (UEW)	999	Unknown	more
V320 — Engine Displacement	2.5 l	—	—
V321 — Engine: Number of Cylinders	04	—	—
V322 — Direct Damage Length (DDL)	999	Unknown	more
V323 — Front-End Overlap % (FEO)	99	Missing or Not applicable	more
V324 — Vehicle Overlap % (VOL)	99	Missing or Not applicable	more

Case Vehicle

General

Variable Number and Name	Code Value	Code Description	Other Options
V401 — VIN	JHLRD1865YC0	—	—
V402 — Manufacturer/Body Code	88114	—	—
V403 — Vehicle Manufacturer	881	Honda	more
V404 — Vehicle Body Code	14	—	—
V405 — Make/Model Code	2351	—	—
V406 — Model Year	2000	—	—
V407 — Vehicle Mass	001452 kg	—	—
V408 — Odometer Reading	028662 miles	—	—
V409 — Number of Occupants	01	—	—
V410 — Traveling Speed	999	Unknown	more
V411 — Body Type	21	Small utility (e.g. Jeep, Scout, Bronco)	more
V412 — Stolen Vehicle	8	Not currently collected	more
V413 — Body Structure	2	Unitized	more
V414 — Transmission Type	1	Automatic	more
V415 — Transmission Lever Location	3	Column	more
V416 — Steering	1	Power	more
V417 — Brakes	1	Power	more
V418 — Brake Type	2	Disc - front wheels	more
V419 — Brake Anti-lock Device	7	Equipped, wheels unknown	more
V420 — Air Conditioning in Vehicle	8	Not currently collected	more
V421 — Drive Type	1	Rear wheel	more
V422 — Dual Rear Wheels	0	No	more
V423 — Original Restraint System Type	3	Airbag	more

V424 — Equipped With Roll Bar	0	No	more
V425 — Roof Type	1	Solid	more
V426 — Wheelbase	262 cm	—	—
V427 — Anti-lacerative Glass	0	None	more
V428 — Average Track Width	153 cm	—	—
V429 — Overall Length	440 cm	—	—
V430 — Overall Width (OAW)	175 cm	—	—
V431 — Front Overhang	084 cm	—	—
V432 — Rear Overhang	094 cm	—	—
V433 — Undeformed End Width (UEW)	156 cm	—	—
V434 — Engine Displacement	2.0 <i>l</i>	—	—
V435 — Engine: Number of Cylinders	04	—	—
V436 — Direct Damage Length (DDL)	032 cm	—	—
V437 — Front End Overlap % (FEO)	21	—	—
V438 — Vehicle Overlap % (VOL)	24	—	—

Case Vehicle

Damage

Description

Variable Number and Name	Code Value	Code Description	Other Options
V501 — Maximum Crush - Front	026 cm	—	—
V502 — Maximum Crush - Right Side	000 cm	No crush (or less than 1 cm.)	more
V503 — Maximum Crush - Rear	000 cm	No crush (or less than 1 cm.)	more
V504 — Maximum Crush - Left Side	000 cm	No crush (or less than 1 cm.)	more
V505 — Maximum Crush - Roof	000 cm	No crush (or less than 1 cm.)	more
V506 — Maximum Crush - Other	000 cm	No crush (or less than 1 cm.)	more
V507 — Are Events In Chronological Order	1	Yes	more
V508 — Event 1 Impact Location	1	On Roadway	more
V509 — Event 1 Impact Configuration	13	FRONT of case veh - SIDE of contacted Vehicle	more
V510 — Event 1 Object/Vehicle Contacted	27	Compact 100-104.9 in. wb.	more
V511 — Event 2 Impact Location	8	No 2nd event	more
V512 — Event 2 Impact Configuration	88	No 2nd event	more
V513 — Event 2 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V514 — Event 3 Impact Location	8	No 3rd event	more
V515 — Event 3 Impact Configuration	88	No 3rd event	more
V516 — Event 3 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V517 — Event 4 Impact Location	8	No 4th event	more
V518 — Event 4 Impact Configuration	88	No 4th event	more
V519 — Event 4 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V520 — Event 5 Impact Location	8	No 5th event	more
V521 — Event 5 Impact Configuration	88	No 5th event	more
V522 — Event 5 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V523 — Event 6 Impact Location	8	No 6th event	more

V524 — Event 6 Impact Configuration	88	No 6th event	more
V525 — Event 6 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V526 — Event 7 Impact On Road	8	No 7th event	more
V527 — Event 7 Impact Configuration	88	No 7th event	more
V528 — Event 7 Object/Vehicle Contacted	00	No object/vehicle contacted	more
V529 — Primary CDC Case Vehicle -event Number	1	Event 1	more
V530 — Primary CDC Case Vehicle - impact speed	999	Unknown	more
V531 — Primary CDC Case Vehicle - Estimated By	1	Investigator	more
V532 — Primary CDC Case Vehicle -crush	026	—	—
V533 — Primary CDC Case Vehicle -clock #1	12	12 o'clock	more
V534 — Primary CDC Case Vehicle letter 1 #1	06	F - Front	more
V535 — Primary CDC Case Vehicle letter 2 #1	18	R - Right (Front or Rear)	more
V536 — Primary CDC Case Vehicle letter 3 #1	05	E - Everything below belt line	more
V537 — Primary CDC Case Vehicle letter 4 #1	05	E - Corner (extends from corner to = or < 16 in [410mm])	more
V538 — Primary CDC Case Vehicle Extent #1	03	Extent 3	more
V539 — Primary CDC Case Vehicle -CDC #1	12FREE3	—	—
V541 — Primary CDC Case Vehicle letter 1 #2	00	Missing Data/Not applicable	more
V542 — Primary CDC Case Vehicle letter 2 #2	00	Missing Data/Not applicable	more
V543 — Primary CDC Case Vehicle letter 3 #2	00	Missing Data/Not applicable	more
V544 — Primary CDC Case Vehicle letter 4 #2	00	Missing Data/Not applicable	more
V545 — Primary CDC Case Vehicle Extent #2	00	Missing Data/Not applicable	more
V546 — Primary CDC Case Vehicle -CDC #2	9800000	—	—
V547 — Primary CDC Contacted Vehicle - Impact Speed	999	Unknown	more
V548 — Primary CDC Contacted Vehicle - Estimated By	1	Investigator	more
V549 — Primary CDC Contacted Vehicle -crush	999	Unknown	more
V550 — Primary CDC Contacted Vehicle -clock #1	99	Unknown or no damage	more

V551 — Primary CDC Contacted Vehicle letter 1 #1	00	Missing Data/Not applicable	more
V552 — Primary CDC Contacted Vehicle letter 2 #1	00	Missing Data/Not applicable	more
V553 — Primary CDC Contacted Vehicle letter 3 #1	00	Missing Data/Not applicable	more
V554 — Primary CDC Contacted Vehicle letter 4 #1	00	Missing Data/Not applicable	more
V555 — Primary CDC Contacted Vehicle Extent #1	00	Missing Data/Not applicable	more
V556 — Primary CDC Contacted Vehicle -CDC #1	9900000	—	—
V558 — Primary CDC Contacted Vehicle letter 1 #2	00	Missing Data/Not applicable	more
V559 — Primary CDC Contacted Vehicle letter 2 #2	00	Missing Data/Not applicable	more
V560 — Primary CDC Contacted Vehicle letter 3 #2	00	Missing Data/Not applicable	more
V561 — Primary CDC Contacted Vehicle letter 4 #2	00	Missing Data/Not applicable	more
V562 — Primary CDC Contacted Vehicle Extent #2	00	Missing Data/Not applicable	more
V563 — Primary CDC Contacted Vehicle -CDC #2	9800000	—	—
V564 — Secondary CDC Case Vehicle - Event No	8	Not applicable	more
V565 — Secondary CDC Case Vehicle - Impact Speed	998	Not Applicable	more
V566 — Secondary CDC Case Vehicle - Estimated By	8	Not applicable (no vehicle/no impact)	more
V567 — Secondary CDC Case Vehicle -crush	998	Not Applicable	more
V568 — Secondary CDC Case Vehicle -clock #1	98	Not Applicable	more
V569 — Secondary CDC Case Vehicle letter 1 #1	00	Missing Data/Not applicable	more
V570 — Secondary CDC Case Vehicle letter 2 #1	00	Missing Data/Not applicable	more
V571 — Secondary CDC Case Vehicle letter 3 #1	00	Missing Data/Not applicable	more
V572 — Secondary CDC Case Vehicle letter 4 #1	00	Missing Data/Not applicable	more
V573 — Secondary CDC Case Vehicle Extent #1	00	Missing Data/Not applicable	more
V574 — Secondary CDC Case Vehicle -CDC #1	9800000	—	—

V576 — Secondary CDC Case Vehicle letter 1 #2	00	Missing Data/Not applicable	more
V577 — Secondary CDC Case Vehicle letter 2 #2	00	Missing Data/Not applicable	more
V578 — Secondary CDC Case Vehicle letter 3 #2	00	Missing Data/Not applicable	more
V579 — Secondary CDC Case Vehicle letter 4 #2	00	Missing Data/Not applicable	more
V580 — Secondary CDC Case Vehicle Extent #2	00	Missing Data/Not applicable	more
V581 — Secondary CDC Case Vehicle -CDC #2	9800000	—	—
V582 — Secondary CDC Contacted Vehicle - Impact Speed	998	Not Applicable	more
V583 — Secondary CDC Contacted Vehicle - Estimated By	8	Not applicable (no vehicle/no impact)	more
V584 — Secondary CDC Contacted Vehicle - crush	998	Not Applicable	more
V585 — Secondary CDC Contacted Vehicle - clock #1	98	Not Applicable	more
V586 — Secondary CDC Contacted Vehicle letter 1 #1	00	Missing Data/Not applicable	more
V587 — Secondary CDC Contacted Vehicle letter 2 #1	00	Missing Data/Not applicable	more
V588 — Secondary CDC Contacted Vehicle letter 3 #1	00	Missing Data/Not applicable	more
V589 — Secondary CDC Contacted Vehicle letter 4 #1	00	Missing Data/Not applicable	more
V590 — Secondary CDC Contacted Vehicle Extent #1	00	Missing Data/Not applicable	more
V591 — Secondary CDC Contacted Vehicle -CDC #1	9800000	—	—
V593 — Secondary CDC Contacted Vehicle letter 1 #2	00	Missing Data/Not applicable	more
V594 — Secondary CDC Contacted Vehicle letter 2 #2	00	Missing Data/Not applicable	more
V595 — Secondary CDC Contacted Vehicle letter 3 #2	00	Missing Data/Not applicable	more
V596 — Secondary CDC Contacted Vehicle letter 4 #2	00	Missing Data/Not applicable	more
V597 — Secondary CDC Contacted Vehicle Extent #2	00	Missing Data/Not applicable	more
V598 — Secondary CDC Contacted Vehicle -CDC #2	9800000	—	—

Crash Severity

Variable Number and Name	Code Value	Code Description	Other Options
V601 — Case Vehicle Primary Impact Number	1	—	—
V602 — Primary Impact Total Delta-V	018 kph	—	—
V603 — Primary Case Vehicle Reconstructed Longitudinal Delta-V	-018 kph	—	—
V604 — Primary Case Vehicle Reconstructed Lateral Delta-V	-003 kph	—	—
V605 — Primary Case Vehicle Reconstructed Crush Energy	0014 kJ	—	—
V606 — Primary Impact Case Vehicle - reconstruction	21	Reconstructed, low confidence level	more
V607 — Primary Case Vehicle Reconstruction Mode	2	CDC & detailed damage	more
V608 — Primary Contacted Vehicle Reconstructed Total Delta-V	017 kph	—	—
V609 — Primary Contacted Vehicle Reconstructed Longitudinal Delta-V	-003 kph	—	—
V610 — Primary Contacted Vehicle Reconstructed Lateral Delta-V	0017 kph	—	—
V611 — Primary Contacted Vehicle Reconstructed Crush Energy	0055 kJ	—	—
V612 — Case Vehicle Secondary Impact Number	8	—	—
V613 — Secondary Case Vehicle Reconstructed Total Delta-V	888	N/A	more
V614 — Secondary Case Vehicle Reconstructed Longitudinal Delta-V	8888	—	—
V615 — Secondary Case Vehicle Reconstructed Lateral Delta-V	8888	—	—
V616 — Secondary Case Vehicle Reconstructed Crush Energy	8888	—	—
V617 — Secondary Case Vehicle Reconstruction Note	88	—	—
V618 — Secondary Case Vehicle Reconstruction Mode	8	Not applicable	more

V619 — Secondary Contacted Vehicle Reconstructed Total Delta-V	888	N/A	more
V620 — Secondary Contacted Vehicle Reconstructed Longitudinal Delta-V	8888	—	—
V621 — Secondary Contacted Vehicle Reconstructed Lateral Delta-V	8888	—	—
V622 — Secondary Contacted Vehicle Reconstructed Crush Energy	8888	—	—
V623 — Case Vehicle Primary Impact Number	1	—	—
V624 — Primary Case Vehicle Reconstructed Total EBS	016 kph	—	—
V625 — Primary Case Vehicle Reconstructed Longitudinal EBS	-016 kph	—	—
V626 — Primary Case Vehicle Reconstructed Lateral EBS	-003 kph	—	—
V627 — Primary Case Vehicle Reconstructed Crush Energy	0016 kJ	—	—
V628 — Primary Case Vehicle Reconstruction Note	21	Reconstructed, low confidence level	more
V629 — Primary Case Vehicle Reconstruction Mode	2	CDC & detailed damage	more
V630 — Primary Contacted Vehicle Reconstruction Total EBS	999	Unknown	more
V631 — Primary Contacted Vehicle Reconstruction Longitudinal EBS	9999	—	—
V632 — Primary Contacted Vehicle Reconstruction Lateral EBS	9999	—	—
V633 — Primary Contacted Vehicle Reconstruction Crush Energy	9999	—	—
V634 — Case Vehicle Secondary Impact Number	8	Not applicable	more
V635 — Secondary Case Vehicle Reconstruction Total EBS	888	N/A	more
V636 — Secondary Case Vehicle Reconstruction Longitudinal EBS	8888	—	—
V637 — Secondary Case Vehicle Reconstruction Lateral EBS	8888	—	—
V638 — Secondary Case Vehicle Reconstruction Crush Energy	8888	—	—
V639 — Secondary Case Vehicle	88	—	—

Reconstruction Note			
V640 — Secondary Case Vehicle Reconstruction Mode	8	Not applicable	more
V641 — Secondary Contacted Vehicle Reconstruction Total EBS	888	N/A	more
V642 — Secondary Contacted Vehicle Reconstruction Longitudinal EBS	8888	—	—
V643 — Secondary Contacted Vehicle Reconstruction Lateral EBS	8888	—	—
V644 — Secondary Contacted Vehicle Reconstruction Crush Energy	8888	—	—
V645 — Case Vehicle Reconstructed Impact Number	1	—	—
V646 — Case Vehicle Impact 1 Plane	1	Bumper	more
V647 — Case Vehicle Impact 1 Direct Damage Length [DDL]	032 cm	—	—
V648 — Case Vehicle Impact 1 Max Crush	026 cm	—	—
V649 — Case Vehicle Impact 1 Field-L	156 cm	—	—
V650 — Case Vehicle Impact 1 C1	000 cm	No Crush	more
V651 — Case Vehicle Impact 1 C2	000 cm	No Crush	more
V652 — Case Vehicle Impact 1 C3	000 cm	No Crush	more
V653 — Case Vehicle Impact 1 C4	000 cm	No Crush	more
V654 — Case Vehicle Impact 1 C5	000 cm	No Crush	more
V655 — Case Vehicle Impact 1 C6	026 cm	—	—
V656 — Case Vehicle Impact 1 +/- D	0062 cm	—	—
V657 — Case Vehicle Reconstructed Impact Number	9	Unknown	more
V658 — Case Vehicle Impact 2 Plane	9	Unknown	more
V659 — Case Vehicle Impact 2 Direct Damage Length [DDL]	999	Unknown	more
V660 — Case Vehicle Impact 2 Max Crush	999	Unknown	more
V661 — Case Vehicle Impact 2 Field-L	999	Unknown	more
V662 — Case Vehicle Impact 2 C1	999	Unknown	more
V663 — Case Vehicle Impact 2 C2	999	Unknown	more
V664 — Case Vehicle Impact 2 C3	999	Unknown	more

V665 — Case Vehicle Impact 2 C4	999	Unknown	more
V666 — Case Vehicle Impact 2 C5	999	Unknown	more
V667 — Case Vehicle Impact 2 C6	999	Unknown	more
V668 — Case Vehicle Impact 2 +/- D	9999	—	—
V669 — Other Vehicle Reconstructed Impact Number	9	Unknown	more
V670 — Other Vehicle Impact 1 Plane	9	Unknown	more
V671 — Other Vehicle Impact 1 Direct Damage Length [DDL]	999	Unknown	more
V672 — Other Vehicle Impact 1 Max Crush	999	Unknown	more
V673 — Other Vehicle Impact 1 Field-L	999	Unknown	more
V674 — Other Vehicle Impact 1 C1	999	Unknown	more
V675 — Other Vehicle Impact 1 C2	999	Unknown	more
V676 — Other Vehicle Impact 1 C3	999	Unknown	more
V677 — Other Vehicle Impact 1 C4	999	Unknown	more
V678 — Other Vehicle Impact 1 C5	999	Unknown	more
V679 — Other Vehicle Impact 1 C6	999	Unknown	more
V680 — Other Vehicle Impact 1 +/- D	9999	—	—
V681 — Other Vehicle Reconstructed Impact Number	9	Unknown	more
V682 — Other Vehicle Impact 2 Plane	9	Unknown	more
V683 — Other Vehicle Impact 2 Direct Damage Length [DDL]	999	Unknown	more
V684 — Other Vehicle Impact 2 Max Crush	999	Unknown	more
V685 — Other Vehicle Impact 2 Field-L	999	Unknown	more
V686 — Other Vehicle Impact 2 C1	999	Unknown	more
V687 — Other Vehicle Impact 2 C2	999	Unknown	more
V688 — Other Vehicle Impact 2 C3	999	Unknown	more
V689 — Other Vehicle Impact 2 C4	999	Unknown	more
V690 — Other Vehicle Impact 2 C5	999	Unknown	more
V691 — Other Vehicle Impact 2 C6	999	Unknown	more
V692 — Other Vehicle Impact 2 +/- D	9999	—	—

Case Vehicle

Tires & Rims

Variable Number and Name	Code Value	Code Description	Other Options
V701 — Left Front Wheel Damaged	0	No	more
V702 — Right Front Wheel Damaged	1	Yes	more
V703 — Right Rear Wheel Damaged	0	No	more
V704 — Left Rear Wheel Damaged	0	No	more
V705 — Left Front Tire Tread Type	4	All Weather	more
V706 — Right Front Tire Tread Type	4	All Weather	more
V707 — Right Rear Tire Tread Type	4	All Weather	more
V708 — Left Rear Tire Tread Type	4	All Weather	more
V709 — Left Front Carcass Construction	3	Radial	more
V710 — Right Front Carcass Construction	3	Radial	more
V711 — Right Rear Carcass Construction	3	Radial	more
V712 — Left Rear Carcass Construction	3	Radial	more
V717 — Left Front Tire Size	P205R15	—	—
V718 — Right Front Tire Size	P205R15	—	—
V719 — Right Rear Tire Size	P205R15	—	—
V720 — Left Rear Tire Size	P205R15	—	—

Case Vehicle

Fuel, Tank, Fire

Variable Number and Name	Code Value	Code Description	Other Options
V801 — Propulsive Fuel Type	1	Gasoline	more
V802 — Main Tank Location	322	Within frame/centered laterally - within vertically	more
V803 — Main Filler Cap Location	113	Left of frame laterally - above vertically	more
V804 — Main Tank Material	1	Steel	more
V805 — Aux Tank Type	8	Not applicable (not equipped)	more
V806 — Aux Tank Location	888	Not applicable (not equipped)	more
V807 — Aux Filler Cap Location	888	Not applicable (not equipped)	more
V808 — Aux Tank Material	8	Not applicable	more
V901 — Fuel Leakage From Crash	0	No	more
V1001 — Fire In Or On Case Vehicle	0	No	more

Case Vehicle

Exterior

Variable Number and Name	Code Value	Code Description	Other Options
V1101 — Hood Latch Released	0	No	more
V1102 — Hood Latch Damaged	0	No	more
V1103 — Hood Latch Jammed	8	Not applicable	more
V1104 — Left Hood Hinge Damaged	0	No	more
V1105 — Left Hood Hinge Separated	8	Not applicable	more
V1106 — Right Hood Hinge Damaged	0	No	more
V1107 — Right Hood Hinge Separated	8	Not applicable	more
V1108 — Hood Remained On Vehicle	1	Yes	more
V1109 — Rear Hood Edge Elevated	0	No	more
V1110 — Edge Contacted Windshield	0	No	more
V1111 — Edge Penetrated Windshield	8	Not applicable	more
V1112 — Hood Latch Location	1	Front of Vehicle	more
V1113 — Eng/Transmissn Mount Separation	0	No	more
V1114 — Steerng Column Flex Coupling	9	Unknown if equipped	more
V1115 — Steerng Column Coupling Damaged	9	Unknown	more
V1116 — Steerng Column Coupling Separated	9	Unknown	more
V1117 — Eng Comp Telescopng Unit	88	Not collected	more
V1118 — Comp Orig/Telescopd Diff	888	Not collected	more
V1119 — Left Side Body Mount Separation	8	Not applicable (unitized)	more

V1120 — Upper Left A-pillar Separation	0	No	more
V1121 — Lower Left A-pillar Separation	0	No	more
V1122 — Upper Left B-pillar Separation	0	No	more
V1123 — Lower Left B-pillar Separation	0	No	more
V1124 — Upper Left C-pillar Separation	0	No	more
V1125 — Lower Left C-pillar Separation	0	No	more
V1126 — Upper Left D-pillar Separation	0	No	more
V1127 — Lower Left D-pillar Separation	0	No	more
V1128 — Left Front Door Opening Cause	0	Door did not open	more
V1129 — Left Rear Door Opening Cause	0	Door did not open	more
V1130 — Left Front Door Jammed Closed	0	No	more
V1131 — Left Rear Door Jammed Closed	0	No	more
V1132 — Rear Door Type	3	Two-way tailgate	more
V1133 — Rear Door Opening Cause	0	Door did not open	more
V1134 — Rear Door Jammed Closed	0	No	more
V1135 — Luggage Partition Damagd	8	Not applicable	more
V1136 — Spare Tire Status	8	Not collected	more
V1137 — Trailer Hitch Type	0	No hitch	more
V1138 — Trailer Type	0	No trailer	more
V1139 — Right Side Body Mount Separation	8	Not applicable (unitized)	more
V1140 — Upper Right A-pillar Separation	0	No	more
V1141 — Lower Right A-pillar Separation	0	No	more
V1142 — Upper Right B-pillar	0	No	more

Separation			
V1143 — Lower Right B-pillar Separation	0	No	more
V1144 — Upper Right C-pillar Separation	0	No	more
V1145 — Lower Right C-pillar Separation	0	No	more
V1146 — Upper Right D-pillar Separation	0	No	more
V1147 — Lower Right D-pillar Separation	0	No	more
V1148 — Right Front Door Opening Cause	00	Door did not open	more
V1149 — Right Rear Door Opening Cause	00	Door did not open	more
V1150 — Right Front Door Jammed Closed	0	No	more
V1151 — Right Rear Door Jammed Closed	0	No	more
V1152 — Van Rear Door Type	8	Not applicable (not a van)	more
V1153 — Windshield Cracked	1	Yes	more
V1154 — Windshield Broken	0	No	more
V1155 — Windshield Cracked or Broken by Occupant	1	Yes	more
V1156 — Bond Separation Extent	0	None	more
V1157 — Windshield Code	97	—	—
V1158 — Did Sun/T Roof Open	8	Not Applicable	more

Case Vehicle

Steering

Column/Rim

Variable Number and Name	Code Value	Code Description	Other Options
V1201 — Steering Wheel Rim Damage	0	None	more
V1202 — Number of Steering Wheel Spokes	4	4 spokes	more
V1203 — Steering Wheel Spoke Damage	0	None	more
V1204 — Column Tilt Feature	2	Up	more
V1205 — Column Swing-away Feature	0	Not equipped	more
V1206 — Column Telescoping Feature	0	Not equipped	more
V1207 — Wheel Energy Absorb Device	8	Not collected	more
V1208 — Wheel Ea Orig/Damaged Diff	888	Not collected	more
V1209 — Column Energy Absorb Device	88	Not collected	more
V1210 — Column Ea Orig/Comprss Diff	888	Not collected	more
V1211 — Shear Capsule Separation	888	Not collected	more
V1212 — Column Vertical Rotation	0	No apparent rotation	more
V1213 — Column Lateral Rotation	0	No apparent rotation	more
V1214 — Steering Wheel Hub Damage	0	None	more

Case Vehicle Intrusion

Variable Number and Name	Code Value	Code Description	Other Options
V1301 — Occupant Compartment Intrusion	0	No	more
V1302 — Was Intrusion Catastrophic	8	Not applicable	more
V1303 — Intrusion Number 01	00	No Intrusion, None	more
V1304 — Intrusion 01 Occupant Space Number	00	No Intrusion, None	more
V1305 — Intrusion 01 Intruding Object	00	No Intrusion, None	more
V1306 — Intrusion 01 Assoc Event Number	0	No Intrusion, None	more
V1307 — Intrusion 01 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1308 — Intrusion 01 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1309 — Intrusion 01 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1310 — Intrusion 01 Occupant Number	00	No contact or no intrusion	more
V1311 — Intrusion 01 Injury Number	00	No injury or no intrusion	more
V1312 — Intrusion 01 Occupant Number	00	No contact or no intrusion	more
V1313 — Intrusion 01 Injury Number	99	Contact, injury unknown or data not collected	more
V1314 — Intrusion Number 02	00	No Intrusion, None	more
V1315 — Intrusion 02 Occupant Space Number	00	No Intrusion, None	more
V1316 — Intrusion 02 Intruding Object	00	No Intrusion, None	more
V1317 — Intrusion 02 Assoc Event Number	0	No Intrusion, None	more
V1318 — Intrusion 02 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1319 — Intrusion 02 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1320 — Intrusion 02 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1321 — Intrusion 02 Occupant Number	00	No contact or no intrusion	more
V1322 — Intrusion 02 Injury Number	00	No injury or no intrusion	more
V1323 — Intrusion 02 Occupant Number	00	No contact or no intrusion	more
V1324 — Intrusion 02 Injury Number	99	Contact, injury unknown or	more

		data not collected	
V1325 — Intrusion Number 03	00	No Intrusion, None	more
V1326 — Intrusion 03 Occupant Space Number	00	No Intrusion, None	more
V1327 — Intrusion 03 Intruding Object	00	No Intrusion, None	more
V1328 — Intrusion 03 Assoc Event Number	0	No Intrusion, None	more
V1329 — Intrusion 03 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1330 — Intrusion 03 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1331 — Intrusion 03 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1332 — Intrusion 03 Occupant Number	00	No contact or no intrusion	more
V1333 — Intrusion 03 Injury Number	00	No injury or no intrusion	more
V1334 — Intrusion 03 Occupant Number	00	No contact or no intrusion	more
V1335 — Intrusion 03 Injury Number	99	Contact, injury unknown or data not collected	more
V1336 — Intrusion Number 04	00	No Intrusion, None	more
V1337 — Intrusion 04 Occupant Space Number	00	No Intrusion, None	more
V1338 — Intrusion 04 Intruding Object	00	No Intrusion, None	more
V1339 — Intrusion 04 Assoc Event Number	0	No Intrusion, None	more
V1340 — Intrusion 04 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1341 — Intrusion 04 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1342 — Intrusion 04 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1343 — Intrusion 04 Occupant Number	00	No contact or no intrusion	more
V1344 — Intrusion 04 Injury Number	00	No injury or no intrusion	more
V1345 — Intrusion 04 Occupant Number	00	No contact or no intrusion	more
V1346 — Intrusion 04 Injury Number	99	Contact, injury unknown or data not collected	more
V1347 — Intrusion Number 05	00	No Intrusion, None	more
V1348 — Intrusion 05 Occupant Space Number	00	No Intrusion, None	more
V1349 — Intrusion 05 Intruding Object	00	No Intrusion, None	more
V1350 — Intrusion 05 Assoc Event Number	0	No Intrusion, None	more

V1351 — Intrusion 05 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1352 — Intrusion 05 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1353 — Intrusion 05 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1354 — Intrusion 05 Occupant Number	00	No contact or no intrusion	more
V1355 — Intrusion 05 Injury Number	00	No injury or no intrusion	more
V1356 — Intrusion 05 Occupant Number	00	No contact or no intrusion	more
V1357 — Intrusion 05 Injury Number	99	Contact, injury unknown or data not collected	more
V1358 — Intrusion Number 06	00	No Intrusion, None	more
V1359 — Intrusion 06 Occupant Space Number	00	No Intrusion, None	more
V1360 — Intrusion 06 Intruding Object	00	No Intrusion, None	more
V1361 — Intrusion 06 Assoc Event Number	0	No Intrusion, None	more
V1362 — Intrusion 06 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1363 — Intrusion 06 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1364 — Intrusion 06 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1365 — Intrusion 06 Occupant Number	00	No contact or no intrusion	more
V1366 — Intrusion 06 Injury Number	00	No injury or no intrusion	more
V1367 — Intrusion 06 Occupant Number	00	No contact or no intrusion	more
V1368 — Intrusion 06 Injury Number	99	Contact, injury unknown or data not collected	more
V1369 — Intrusion Number 07	00	No Intrusion, None	more
V1370 — Intrusion 07 Occupant Space Number	00	No Intrusion, None	more
V1371 — Intrusion 07 Intruding Object	00	No Intrusion, None	more
V1372 — Intrusion 07 Assoc Event Number	0	No Intrusion, None	more
V1373 — Intrusion 07 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1374 — Intrusion 07 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1375 — Intrusion 07 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1376 — Intrusion 07 Occupant Number	00	No contact or no intrusion	more
V1377 — Intrusion 07 Injury Number	00	No injury or no intrusion	more
V1378 — Intrusion 07 Occupant Number	00	No contact or no intrusion	more

V1379 — Intrusion 07 Injury Number	99	Contact, injury unknown or data not collected	more
V1380 — Intrusion Number 08	00	No Intrusion, None	more
V1381 — Intrusion 08 Occupant Space Number	00	No Intrusion, None	more
V1382 — Intrusion 08 Intruding Object	00	No Intrusion, None	more
V1383 — Intrusion 08 Assoc Event Number	0	No Intrusion, None	more
V1384 — Intrusion 08 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1385 — Intrusion 08 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1386 — Intrusion 08 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1387 — Intrusion 08 Occupant Number	00	No contact or no intrusion	more
V1388 — Intrusion 08 Injury Number	00	No injury or no intrusion	more
V1389 — Intrusion 08 Occupant Number	00	No contact or no intrusion	more
V1390 — Intrusion 08 Injury Number	99	Contact, injury unknown or data not collected	more
V1391 — Intrusion Number 09	00	No Intrusion, None	more
V1392 — Intrusion 09 Occupant Space Number	00	No Intrusion, None	more
V1393 — Intrusion 09 Intruding Object	00	No Intrusion, None	more
V1394 — Intrusion 09 Assoc Event Number	0	No Intrusion, None	more
V1395 — Intrusion 09 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1396 — Intrusion 09 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1397 — Intrusion 09 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1398 — Intrusion 09 Occupant Number	00	No contact or no intrusion	more
V1399 — Intrusion 09 Injury Number	00	No injury or no intrusion	more
V1400 — Intrusion 09 Occupant Number	00	No contact or no intrusion	more
V1401 — Intrusion 09 Injury Number	99	Contact, injury unknown or data not collected	more
V1402 — Intrusion Number 10	00	No Intrusion, None	more
V1403 — Intrusion 10 Occupant Space Number	00	No Intrusion, None	more
V1404 — Intrusion 10 Intruding Object	00	No Intrusion, None	more
V1405 — Intrusion 10 Assoc Event Number	0	No Intrusion, None	more

V1406 — Intrusion 10 Max Intrusion X-axis	00 cm	0 cm or No Intrusion	more
V1407 — Intrusion 10 Max Intrusion Y-axis	00 cm	0 cm or No Intrusion	more
V1408 — Intrusion 10 Max Intrusion Z-axis	00 cm	0 cm or No Intrusion	more
V1409 — Intrusion 10 Occupant Number	00	No contact or no intrusion	more
V1410 — Intrusion 10 Injury Number	00	No injury or no intrusion	more
V1411 — Intrusion 10 Occupant Number	00	No contact or no intrusion	more
V1412 — Intrusion 10 Injury Number	99	Contact, injury unknown or data not collected	more
V1413 — Door Intrusion Number 01	88	Not Applicable	more
V1414 — Door Intrusion Number 01 Cause	8	Not applicable	more
V1415 — Door Intrusion Number 02	88	Not Applicable	more
V1416 — Door Intrusion Number 02 Cause	8	Not applicable	more
V1417 — Door Intrusion Number 03	88	Not Applicable	more
V1418 — Door Intrusion Number 03 Cause	8	Not applicable	more
V1419 — Door Intrusion 01 Component	88	Not Applicable	more
V1420 — Door Intrusion 01 Component Damaged 1	8	Not Applicable	more
V1421 — Door Intrusion 01 Component Damaged 2	8	Not Applicable	more
V1422 — Door Intrusion 02 Component	88	Not Applicable	more
V1423 — Door Intrusion 02 Component Damaged 1	8	Not Applicable	more
V1424 — Door Intrusion 02 Component Damaged 2	8	Not Applicable	more
V1425 — Door Intrusion 03 Component	88	Not Applicable	more
V1426 — Door Intrusion 03 Component Damaged 1	8	Not Applicable	more
V1427 — Door Intrusion 03 Component Damaged 2	8	Not Applicable	more
V1428 — Door Intrusion 04 Component	88	Not Applicable	more
V1429 — Door Intrusion 04 Component Damaged 1	8	Not Applicable	more
V1430 — Door Intrusion 04 Component Damaged 2	8	Not Applicable	more

Case Vehicle Airbag(s)

Variable Number and Name	Code Value	Code Description	Other Options
V1501 — Driver Airbag Equipped	1	Yes	more
V1502 — Driver Airbag Deployed	1	Yes	more
V1503 — Driver Airbag Condition	0	No Damage	more
V1504 — Passenger Airbag Equip	1	Yes	more
V1505 — Passenger Airbag Deployed	1	Yes	more
V1506 — Passenger Airbag Condition	0	No Damage	more
V1507 — Steering Wheel Airbag Tether	1	Yes	more
V1508 — Driver Airbag Marked By Contact	0	No	more
V1509 — Passenger Airbag Tether	0	No	more
V1510 — Passenger Airbag Marked By Contact	0	No	more

Case Vehicle

Interior

Variable Number and Name	Code Value	Code Description	Other Options
V1601 — Left Front Door Damaged	0	No	more
V1602 — Right Front Door Damaged	0	No	more
V1603 — Left Front Hardware Damaged	0	No	more
V1604 — Right Front Hardware Damaged	0	No	more
V1605 — Left Front Armrest Damaged	0	No	more
V1606 — Right Front Armrest Damaged	0	No	more
V1607 — Left Front Glass Damaged	0	No	more
V1608 — Right Front Glass Damaged	0	No	more
V1609 — Left Rear Door Area Damaged	0	No	more
V1610 — Right Rear Door Area Damaged	0	No	more
V1611 — Left Rear Hardware Damaged	0	No	more
V1612 — Right Rear Hardware Damaged	0	No	more
V1613 — Left Rear Armrest Damaged	0	No	more
V1614 — Right Rear Armrest Damaged	0	No	more
V1615 — Left Rear Glass Damaged	0	No	more
V1616 — Right Rear Glass Damaged	0	No	more
V1617 — Left Roof Side Rail Damaged	0	No	more
V1618 — Right Roof Side Rail Damaged	0	No	more

V1619 — Left B-pillar Damaged	0	No	more
V1620 — Right B-pillar Damaged	0	No	more
V1621 — Left C-pillar Damaged	0	No	more
V1622 — Right C-pillar Damaged	0	No	more
V1623 — Left D-pillar Damaged	0	No	more
V1624 — Right D-pillar Damaged	0	No	more
V1625 — Left Headlining Damaged	0	No	more
V1626 — Right Headlining Damaged	0	No	more
V1627 — Left Roof Structure Damaged	0	No	more
V1628 — Right Roof Structure Damaged	0	No	more
V1629 — Left T/Sun Roof Damaged	8	Not applicable	more
V1630 — Right T/Sun Roof Damaged	8	Not applicable	more
V1631 — Other Left Side Item Damagd	8	Not applicable	more
V1632 — Other Right Side Item Damagd	8	Not applicable	more
V1633 — Foot Controls Damaged	0	No	more
V1634 — Ignition Key Damaged	0	No	more
V1635 — Rear View Mirror Damaged	1	Yes	more
V1636 — Sunvisor/Fitting Damaged	0	No	more
V1637 — Windshield Molding Damaged	0	No	more
V1638 — Left A-pillar Damaged	0	No	more
V1639 — Right A-pillar Damaged	0	No	more
V1640 — Center Console Damaged	0	No	more
V1641 — Transmission Lever Damaged	0	No	more
V1642 — Horn/Spoke Shroud Damagd	0	No	more
V1643 — Upper Panel Damaged	0	No	more

V1644 — Mid Panel Damaged	0	No	more
V1645 — Lower Panel Damaged	4	Yes, occupant contact	more
V1646 — Ashtray Damaged	0	No	more
V1647 — Control Knob/Lever Damaged	0	No	more
V1648 — Glove Compartment Area Damaged	0	No	more
V1649 — Instruments Damaged	0	No	more
V1650 — Park Brake Release Damaged	0	No	more
V1651 — Park Brake Pedal Damaged	0	No	more
V1652 — A/C Or Upper Vent Damaged	0	No	more
V1653 — Heater Or A/C Duct Damaged	0	No	more
V1654 — Radio Damaged	0	No	more
V1655 — Other Item Damaged	8	Not applicable	more
V1656 — Rear Window Damaged	0	No	more
V1657 — Rear Window Header Damaged	0	No	more
V1658 — Vertical Console Damaged	0	No	more
V1659 — Roof Console Damaged	0	No	more

Case Vehicle





Seats

Variable Number and Name	Code Value	Code Description	Other Options
V1701 — Driver Front Seat Type	05	Bucket	more
V1702 — Passenger Front Seat Type	05	Bucket	more
V1703 — Driver Seat Mount Type	1	Standard	more
V1704 — Passenger Seat Mount Type	1	Standard	more
V1705 — Driver Swivel Mechanism Equipped	0	No	more
V1706 — Passenger Swivel Mechanism Equipped	0	No	more
V1707 — Driver Seat Original Equipment	1	Yes	more
V1708 — Passenger Seat Original Equipment	1	Yes	more
V1709 — Driver Seat/Rear Occupant Contact	8	Not applicable	more
V1710 — Passenger Seat/Rear Occupant Contact	8	Not applicable	more
V1711 — Driver Seat Damage	0	None	more
V1712 — Passenger Seat Damage	0	None	more
V1713 — Center Front Armrest Damaged	8	Not applicable (no center armrest)	more
V1714 — Driver Seat Rotation	0	None apparent	more
V1715 — Passenger Seat Rotation	0	None apparent	more
V1716 — Driver Seat-back Type	3	Reclining	more
V1717 — Passenger Seat-back Type	3	Reclining	more
V1718 — Driver Seat-back Lock Type	1	Manual	more
V1719 — Passenger Seat-back Lock Type	1	Manual	more
V1720 — Driver Seat-back Lock Held	1	Yes	more
V1721 — Passenger Seat-back Lock Held	1	Yes	more
V1722 — Driver Recliner Mechanism Held	1	Yes	more

V1723 — Passenger Recliner Mechanism Held	1	Yes	more
V1724 — Driver Head Restraint Type	1	Adjustable	more
V1725 — Passenger Head Restraint Type	1	Adjustable	more
V1726 — Driver Head Rest Removed	0	No	more
V1727 — Passenger Head Rest Removed	0	No	more
V1728 — Driver Head Rest Adjustment	1	Up	more
V1729 — Passenger Head Rest Adjustment	1	Up	more
V1730 — Driver Head Rest Damage	0	None	more
V1731 — Passenger Head Rest Damage	0	None	more
V1732 — Driver Seat Adjustment Type	1	Manual	more
V1733 — Passenger Seat Adjustment Type	1	Manual	more
V1734 — Driver Seat Adjustment Provided	2	4-way	more
V1735 — Passenger Seat Adjustment Provided	2	4-way	more
V1736 — Driver Seat Adjuster Damage	0	None	more
V1737 — Passenger Seat Adjuster Damage	0	None	more
V1738 — Driver Seat Adjuster Separation	8	Not applicable	more
V1739 — Passenger Seat Adjuster Separation	8	Not applicable	more
V1740 — Driver Seat Pre-crash Position	2	Middle	more
V1741 — Passenger Seat Pre-crash Position	3	Rearward	more
V1742 — Left Rear Seat Type	2	Folding	more
V1743 — Right Rear Seat Type	2	Folding	more
V1744 — Left Rear Seat Damaged	0	None	more
V1745 — Right Rear Seat Damaged	0	None	more
V1746 — Center Rear Armrest Damaged	0	No	more
V1747 — Left Rear Seat-back Left Lock Equipped	1	Yes	more
V1748 — Right Rear Seat-back Left Lock Equipped	0	No	more

V1749 — Left Rear Seat-back Left Lock Held	0	No	more
V1750 — Right Rear Seat-back Left Lock Held	8	Not applicable	more
V1751 — Left Rear Seat-back Right Lock Equipped	0	No	more
V1752 — Right Rear Seat-back Right Lock Equipped	1	Yes	more
V1753 — Left Rear Seat-back Right Lock Held	8	Not applicable	more
V1754 — Right Rear Seat-back Right Lock Held	0	No	more
V1755 — Left 3rd Seat Equipped	0	No	more
V1756 — Right 3rd Seat Equipped	0	No	more
V1757 — Left 3rd Seat Backrest Damaged	8	Not applicable	more
V1758 — Right 3rd Seat Backrest Damaged	8	Not applicable	more
V1759 — Left 3rd Seat Cushion Damaged	8	Not applicable	more
V1760 — Right 3rd Seat Cushion Damaged	8	Not applicable	more
V1761 — Rear Head Restraints	1	Equipped	more


MEASUREMENTS IN CENTIMETERS



WINDSHIELD MARK ON CASE VEHICLE:



Spider web with
oil deposit






1 = Definitely 2 = Probably 3 = Possible

INTRUSION IT-1


Location of Intrusion	Intruded Component	(All Measurements Are in Centimeters)			Dominant Crush Direction
		Comparison Value	–	Intruded Value = Intrusion	
	None Apparent		–	=	
			–	=	
			–	=	
			–	=	
			–	=	
			–	=	
			–	=	
			–	=	
			–	=	
			–	=	

OCCUPANT CONTACT WORKSHEET


Contact	Interior Component Contacted	Occupant No. if Known	Body Region if Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	Knee bolster	1	Knee	Scuff mark	1
B	Windshield	1	Head	Spider web & oil smear	1
C	Knee bolster	1	Knee	Dent	3
D					
E					
F					
G					
H					
I					



Driver Airbag




Driver Airbag Doors



Vents: ☒ Y N
if yes, how many: 2

Tethers: ☒ Y N
if yes, how many: 2

Passenger Airbag




Vents: ☒ Y ☐ N
if yes, how many: 1

Tethers: Y ☒ N
if yes, how many:

Passenger Airbag Doors

Single Door



Case # 277: Occupant # 1; Injury # 1

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	01	Injury #1	more
V2102 — 1st Prob Contact Area	87	Air cushion skin "airbag"	more
V2103 — 2nd Prob Contact Area	12	Windshield	more
V2104 — Primary OIC -body Region	06	Face	more
V2105 — Primary OIC -aspect	19	Superior/upper	more
V2106 — Primary OIC -lesion	01	Abrasion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	FSAI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 277: Occupant # 1; Injury # 2

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	02	Injury #2	more
V2102 — 1st Prob Contact Area	87	Air cushion skin "airbag"	more
V2103 — 2nd Prob Contact Area	12	Windshield	more
V2104 — Primary OIC -body Region	06	Face	more
V2105 — Primary OIC -aspect	19	Superior/upper	more
V2106 — Primary OIC -lesion	03	Contusion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	FSCI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 277: Occupant # 1; Injury # 3

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	03	Injury #3	more
V2102 — 1st Prob Contact Area	87	Air cushion skin "airbag"	more
V2103 — 2nd Prob Contact Area	38	Other (e.g. fire)	more
V2104 — Primary OIC -body Region	06	Face	more
V2105 — Primary OIC -aspect	12	Left	more
V2106 — Primary OIC -lesion	03	Contusion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	FLCI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 277: Occupant # 1; Injury # 4

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	04	Injury #4	more
V2102 — 1st Prob Contact Area	87	Air cushion skin "airbag"	more
V2103 — 2nd Prob Contact Area	00	No Contact/not applicable	more
V2104 — Primary OIC -body Region	18	Forearm	more
V2105 — Primary OIC -aspect	18	Right	more
V2106 — Primary OIC -lesion	03	Contusion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	RRCI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 277: Occupant # 1; Injury # 5

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	05	Injury #5	more
V2102 — 1st Prob Contact Area	87	Air cushion skin "airbag"	more
V2103 — 2nd Prob Contact Area	00	No Contact/not applicable	more
V2104 — Primary OIC -body Region	18	Forearm	more
V2105 — Primary OIC -aspect	18	Right	more
V2106 — Primary OIC -lesion	01	Abrasion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	RRAI 1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 277: Occupant # 1; Injury # 6

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	06	Injury #6	more
V2102 — 1st Prob Contact Area	87	Air cushion skin "airbag"	more
V2103 — 2nd Prob Contact Area	12	Windshield	more
V2104 — Primary OIC -body Region	05	Elbow	more
V2105 — Primary OIC -aspect	18	Right	more
V2106 — Primary OIC -lesion	03	Contusion	more
V2107 — Primary OIC -system/Organ	09	Integumentary	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	ERCI1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 277: Occupant # 1; Injury # 7

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	07	Injury #7	more
V2102 — 1st Prob Contact Area	98	Impact force, "whiplash", hyperextension/ compression	more
V2103 — 2nd Prob Contact Area	00	No Contact/not applicable	more
V2104 — Primary OIC -body Region	14	Neck	more
V2105 — Primary OIC -aspect	16	Posterior/back	more
V2106 — Primary OIC -lesion	20	Strain	more
V2107 — Primary OIC -system/Organ	13	Muscles	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	NPTM1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 277: Occupant # 1; Injury # 8

Variable Number and Name	Code Value	Code Description	Other Options
V2101 — Injury Number	08	Injury #8	more
V2102 — 1st Prob Contact Area	98	Impact force, "whiplash", hyperextension/ compression	more
V2103 — 2nd Prob Contact Area	00	No Contact/not applicable	more
V2104 — Primary OIC -body Region	02	Back	more
V2105 — Primary OIC -aspect	19	Superior/upper	more
V2106 — Primary OIC -lesion	20	Strain	more
V2107 — Primary OIC -system/Organ	13	Muscles	more
V2108 — Primary OIC -severity	1	Minor	more
V2109 — Primary OIC	BSTM1	—	—
V2110 — Assoc OIC 1 -body Region	99	No injury	more
V2111 — Assoc OIC 1 -aspect	99	No injury	more
V2112 — Assoc OIC 1 -lesion	99	No injury	more
V2113 — Assoc OIC 1 -system/Organ	99	No injury	more
V2114 — Assoc OIC 1 -severity	9	Unknown	more
V2115 — Assoc OIC 1	—	—	—

Case # 277: Occupant # 1

Variable Number and Name	Code Value	Code Description	Other Options
V2001 — Occupant Number	01	Occupant #1	more
V2002 — Occupant Role At 1st Impact	1	Motor vehicle driver	more
V2003 — Occupant Position -row	1	1st row	more
V2004 — Occupant Position -lateral	1	Left	more
V2005 — Occupant Position -posture	10	Sitting on seat	more
V2006 — Occupant Age In Years	53	—	—
V2007 — Occupant Age In Months	25	25 months or older	more
V2008 — Occupant Mass	061 kg	—	—
V2009 — Occupant Height	168 cm	—	—
V2010 — Occupant Sex	2	Female	more
V2011 — Occupant Treatment/Mortality	00	None	more
V2012 — Injury Severity Score	03	ISS 3	more
V2013 — Non-impact Med Condition	0	None	more
V2014 — Police Injury Severity	2	B - Non-incapacitating Injury	more
V2015 — Active Restraint System	3	Both lap belt and shoulder harness	more
V2016 — Active Restraint Usage	0	None (available but not used)	more
V2017 — Passive Restraint System	1	Air bag installed	more
V2018 — Passive Restraint Usage	2	Air bag deployed	more
V2019 — Child Seat Type	88	Not applicable (adult or older child)	more
V2020 — Occupant Ejection Degree	0	None	more
V2021 — Occupant Ejection Area	98	Not applicable (not ejected)	more
V2022 — Highest OIC Severity	1	Minor	more

V2023 — Head Restraint Available	1	Equipped	more
V2024 — Occupant Eyewear	1	Glasses	more
V2025 — Source of Occupant Info	7	Combination of above	more





























BBAJ031
PF9821C.2
141290









RESUME
acc
SET
decel

2 3 4 5 6 7 8 9 10 1 2 3
2m 3m 4m 5m 6m 7m 8m 9m 10m 11m 12m 13m 14m 15m 16m 17m 18m 19m 20m 21m 22m 23m 24m 25m 26m 27m 28m 29m 30m 31m 32m 33m 34m 35m 36m 37m 38m 39m 40m 41m 42m 43m 44m 45m 46m 47m 48m 49m 50m 51m 52m 53m 54m 55m 56m 57m 58m 59m 60m 61m 62m 63m 64m 65m 66m 67m 68m 69m 70m 71m 72m 73m 74m 75m 76m 77m 78m 79m 80m 81m 82m 83m 84m 85m 86m 87m 88m 89m 90m 91m 92m 93m 94m 95m 96m 97m 98m 99m 100m 101m 102m 103m 104m 105m 106m 107m 108m 109m 110m 111m 112m 113m 114m 115m 116m 117m 118m 119m 120m 121m 122m 123m 124m 125m 126m 127m 128m 129m 130m 131m 132m 133m 134m 135m 136m 137m 138m 139m 140m 141m 142m 143m 144m 145m 146m 147m 148m 149m 150m 151m 152m 153m 154m 155m 156m 157m 158m 159m 160m 161m 162m 163m 164m 165m 166m 167m 168m 169m 170m 171m 172m 173m 174m 175m 176m 177m 178m 179m 180m 181m 182m 183m 184m 185m 186m 187m 188m 189m 190m 191m 192m 193m 194m 195m 196m 197m 198m 199m 200m 201m 202m 203m 204m 205m 206m 207m 208m 209m 210m 211m 212m 213m 214m 215m 216m 217m 218m 219m 220m 221m 222m 223m 224m 225m 226m 227m 228m 229m 230m 231m 232m 233m 234m 235m 236m 237m 238m 239m 240m 241m 242m 243m 244m 245m 246m 247m 248m 249m 250m 251m 252m 253m 254m 255m 256m 257m 258m 259m 260m 261m 262m 263m 264m 265m 266m 267m 268m 269m 270m 271m 272m 273m 274m 275m 276m 277m 278m 279m 280m 281m 282m 283m 284m 285m 286m 287m 288m 289m 290m 291m 292m 293m 294m 295m 296m 297m 298m 299m 300m 301m 302m 303m 304m 305m 306m 307m 308m 309m 310m 311m 312m 313m 314m 315m 316m 317m 318m 319m 320m 321m 322m 323m 324m 325m 326m 327m 328m 329m 330m 331m 332m 333m 334m 335m 336m 337m 338m 339m 340m 341m 342m 343m 344m 345m 346m 347m 348m 349m 350m 351m 352m 353m 354m 355m 356m 357m 358m 359m 360m 361m 362m 363m 364m 365m 366m 367m 368m 369m 370m 371m 372m 373m 374m 375m 376m 377m 378m 379m 380m 381m 382m 383m 384m 385m 386m 387m 388m 389m 390m 391m 392m 393m 394m 395m 396m 397m 398m 399m 400m 401m 402m 403m 404m 405m 406m 407m 408m 409m 410m 411m 412m 413m 414m 415m 416m 417m 418m 419m 420m 421m 422m 423m 424m 425m 426m 427m 428m 429m 430m 431m 432m 433m 434m 435m 436m 437m 438m 439m 440m 441m 442m 443m 444m 445m 446m 447m 448m 449m 450m 451m 452m 453m 454m 455m 456m 457m 458m 459m 460m 461m 462m 463m 464m 465m 466m 467m 468m 469m 470m 471m 472m 473m 474m 475m 476m 477m 478m 479m 480m 481m 482m 483m 484m 485m 486m 487m 488m 489m 490m 491m 492m 493m 494m 495m 496m 497m 498m 499m 500m 501m 502m 503m 504m 505m 506m 507m 508m 509m 510m 511m 512m 513m 514m 515m 516m 517m 518m 519m 520m 521m 522m 523m 524m 525m 526m 527m 528m 529m 530m 531m 532m 533m 534m 535m 536m 537m 538m 539m 540m 541m 542m 543m 544m 545m 546m 547m 548m 549m 550m 551m 552m 553m 554m 555m 556m 557m 558m 559m 560m 561m 562m 563m 564m 565m 566m 567m 568m 569m 570m 571m 572m 573m 574m 575m 576m 577m 578m 579m 580m 581m 582m 583m 584m 585m 586m 587m 588m 589m 590m 591m 592m 593m 594m 595m 596m 597m 598m 599m 600m 601m 602m 603m 604m 605m 606m 607m 608m 609m 610m 611m 612m 613m 614m 615m 616m 617m 618m 619m 620m 621m 622m 623m 624m 625m 626m 627m 628m 629m 630m 631m 632m 633m 634m 635m 636m 637m 638m 639m 640m 641m 642m 643m 644m 645m 646m 647m 648m 649m 650m 651m 652m 653m 654m 655m 656m 657m 658m 659m 660m 661m 662m 663m 664m 665m 666m 667m 668m 669m 670m 671m 672m 673m 674m 675m 676m 677m 678m 679m 680m 681m 682m 683m 684m 685m 686m 687m 688m 689m 690m 691m 692m 693m 694m 695m 696m 697m 698m 699m 700m 701m 702m 703m 704m 705m 706m 707m 708m 709m 710m 711m 712m 713m 714m 715m 716m 717m 718m 719m 720m 721m 722m 723m 724m 725m 726m 727m 728m 729m 730m 731m 732m 733m 734m 735m 736m 737m 738m 739m 740m 741m 742m 743m 744m 745m 746m 747m 748m 749m 750m 751m 752m 753m 754m 755m 756m 757m 758m 759m 760m 761m 762m 763m 764m 765m 766m 767m 768m 769m 770m 771m 772m 773m 774m 775m 776m 777m 778m 779m 780m 781m 782m 783m 784m 785m 786m 787m 788m 789m 790m 791m 792m 793m 794m 795m 796m 797m 798m 799m 800m 801m 802m 803m 804m 805m 806m 807m 808m 809m 810m 811m 812m 813m 814m 815m 816m 817m 818m 819m 820m 821m 822m 823m 824m 825m 826m 827m 828m 829m 830m 831m 832m 833m 834m 835m 836m 837m 838m 839m 840m 841m 842m 843m 844m 845m 846m 847m 848m 849m 850m 851m 852m 853m 854m 855m 856m 857m 858m 859m 860m 861m 862m 863m 864m 865m 866m 867m 868m 869m 870m 871m 872m 873m 874m 875m 876m 877m 878m 879m 880m 881m 882m 883m 884m 885m 886m 887m 888m 889m 890m 891m 892m 893m 894m 895m 896m 897m 898m 899m 900m 901m 902m 903m 904m 905m 906m 907m 908m 909m 910m 911m 912m 913m 914m 915m 916m 917m 918m 919m 920m 921m 922m 923m 924m 925m 926m 927m 928m 929m 930m 931m 932m 933m 934m 935m 936m 937m 938m 939m 940m 941m 942m 943m 944m 945m 946m 947m 948m 949m 950m 951m 952m 953m 954m 955m 956m 957m 958m 959m 960m 961m 962m 963m 964m 965m 966m 967m 968m 969m 970m 971m 972m 973m 974m 975m 976m 977m 978m 979m 980m 981m 982m 983m 984m 985m 986m 987m 988m 989m 990m 991m 992m 993m 994m 995m 996m 997m 998m 999m 1000m 1001m 1002m 1003m 1004m 1005m 1006m 1007m 1008m 1009m 1010m 1011m 1012m 1013m 1014m 1015m 1016m 1017m 1018m 1019m 1020m 1021m 1022m 1023m 1024m 1025m 1026m 1027m 1028m 1029m 1030m 1031m 1032m 1033m 1034m 1035m 1036m 1037m 1038m 1039m 1040m 1041m 1042m 1043m 1044m 1045m 1046m 1047m 1048m 1049m 1050m 1051m 1052m 1053m 1054m 1055m 1056m 1057m 1058m 1059m 1060m 1061m 1062m 1063m 1064m 1065m 1066m 1067m 1068m 1069m 1070m 1071m 1072m 1073m 1074m 1075m 1076m 1077m 1078m 1079m 1080m 1081m 1082m 1083m 1084m 1085m 1086m 1087m 1088m 1089m 1090m 1091m 1092m 1093m 1094m 1095m 1096m 1097m 1098m 1099m 1100m 1101m 1102m 1103m 1104m 1105m 1106m 1107m 1108m 1109m 1110m 1111m 1112m 1113m 1114m 1115m 1116m 1117m 1118m 1119m 1120m 1121m 1122m 1123m 1124m 1125m 1126m 1127m 1128m 1129m 1130m 1131m 1132m 1133m 1134m 1135m 1136m 1137m 1138m 1139m 1140m 1141m 1142m 1143m 1144m 1145m 1146m 1147m 1148m 1149m 1150m 1151m 1152m 1153m 1154m 1155m 1156m 1157m 1158m 1159m 1160m 1161m 1162m 1163m 1164m 1165m 1166m 1167m 1168m 1169m 1170m 1171m 1172m 1173m 1174m 1175m 1176m 1177m 1178m 1179m 1180m 1181m 1182m 1183m 1184m 1185m 1186m 1187m 1188m 1189m 1190m 1191m 1192m 1193m 1194m 1195m 1196m 1197m 1198m 1199m 1200m 1201m 1202m 1203m 1204m 1205m 1206m 1207m 1208m 1209m 1210m 1211m 1212m 1213m 1214m 1215m 1216m 1217m 1218m 1219m 1220m 1221m 1222m 1223m 1224m 1225m 1226m 1227m 1228m 1229m 1230m 1231m 1232m 1233m 1234m 1235m 1236m 1237m 1238m 1239m 1240m 1241m 1242m 1243m 1244m 1245m 1246m 1247m 1248m 1249m 1250m 1251m 1252m 1253m 1254m 1255m 1256m 1257m 1258m 1259m 1260m 1261m 1262m 1263m 1264m 1265m 1266m 1267m 1268m 1269m 1270m 1271m 1272m 1273m 1274m 1275m 1276m 1277m 1278m 1279m 1280m 1281m 1282m 1283m 1284m 1285m 1286m 1287m 1288m 1289m 1290m 1291m 1292m 1293m 1294m 1295m 1296m 1297m 1298m 1299m 1300m 1301m 1302m 1303m 1304m 1305m 1306m 1307m 1308m 1309m 1310m 1311m 1312m 1313m 1314m 1315m 1316m 1317m 1318m 1319m 1320m 1321m 1322m 1323m 1324m 1325m 1326m 1327m 1328m 1329m 1330m 1331m 1332m 1333m 1334m 1335m 1336m 1337m 1338m 1339m 1340m 1341m 1342m 1343m 1344m 1345m 1346m 1347m 1348m 1349m 1350m 1351m 1352m 1353m 1354m 1355m 1356m 1357m 1358m 1359m 1360m 1361m 1362m 1363m 1364m 1365m 1366m 1367m 1368m 1369m 1370m 1371m 1372m 1373m 1374m 1375m 1376m 1377m 1378m 1379m 1380m 1381m 1382m 1383m 1384m 1385m 1386m 1387m 1388m 1389m 1390m 1391m 1392m 1393m 1394m 1395m 1396m 1397m 1398m 1399m 1400m 1401m 1402m 1403m 1404m 1405m 1406m 1407m 1408m 1409m 1410m 1411m 1412m 1413m 1414m 1415m 1416m 1417m 1418m 1419m 1420m 1421m 1422m 1423m 1424m 1425m 1426m 1427m 1428m 1429m 1430m 1431m 1432m 1433m 1434m 1435m 1436m 1437m 1438m 1439m 1440m 1441m 1442m 1443m 1444m 1445m 1446m 1447m 1448m 1449m 1450m 1451m 1452m 1453m 1454m 1455m 1456m 1457m 1458m 1459m 1460m 1461m 1462m 1463m 1464m 1465m 1466m 1467m 1468m 1469m 1470m 1471m 1472m 1473m 1474m 1475m 1476m 1477m 1478m 1479m 1480m 1481m 1482m 1483m 1484m 1485m 1486m 1487m 1488m 1489m 1490m 1491m 1492m 1493m 1494m 1495m 1496m 1497m 1498m 1499m 1500m 1501m 1502m 1503m 1504m 1505m 1506m 1507m 1508m 1509m 1510m 1511m 1512m 1513m 1514m 1515m 1516m 1517m 1518m 1519m 1520m 1521m 1522m 1523m 1524m 1525m 1526m 1527m 1528m 1529m 1530m 1531m 1532m 1533m 1534m 1535m 1536m 1537m 1538m 1539m 1540m 1541m 1542m 1543m 1544m 1545m 1546m 1547m 1548m 1549m 1550m 1551m 1552m 1553m 1554m 1555m 1556m 1557m 1558m 1559m 1560m 1561m 1562m 1563m 1564m 1565m 1566m 1567m 1568m 1569m 1570m 1571m 1572m 1573m 1574m 1575m 1576m 1577m 1578m 1579m 1580m 1581m 1582m 1583m 1584m 1585m 1586m 1587m 1588m 1589m 1590m 1591m 1592m 1593m 1594m 1595m 1596m 1597m 1598m 1599m 1600m 1601m 1602m 1603m 1604m 1605m 1606m 1607m 1608m 1609m 1610m 1611m 1612m 1613m 1614m 1615m 1616m 1617m 1618m 1619m 1620m 1621m 1622m 1623m 1624m 1625m 1626m 1627m 1628m 1629m 1630m 1631m 1632m 1633m 1634m 1635m 1636m 1637m 1638m 1639m 1640m 1641m 1642m 1643m 1644m 1645m 1646m 1647m 1648m 1649m 1650m 1651m 1652m 1653m 1654m 1655m 1656m 1657m 1658m 1659m 1660m 1661m 1662m 1663m 1664m 1665m 1666m 1667m 1668m 1669m 1670m 1671m 1672m 1673m 1674m 1675m 1676m 1677m 1678m 1679m 1680m 1681m 1682m 1683m 1684m 1685m 1686m 1687m 1688m 1689m 1690m 1691m 1692m 1693m 1694m 1695m 1696m 1697m 1698m 1699m 1700m 1701m 1702m 1703m 1704m 1705m 1706m 1707m 1708m 1709m 1710m 1711m 1712m 1713m 1714m 1715m 1716m 1717m 1718m 1719m 1720m 1721m 1722m 1723m 1724m 1725m 1726m 1727m 1728m 1729m 1730m 1731m 1732m 1733m 1734m 1735m 1736m 1737m 1738m 1739m 1740m 1741m 1742m 1743m 1744m 1745m 1746m 1747m 1748m 1749m 1750m 1751m 1752m 1753m 1754m 1755m 1756m 1757m 1758m 1759m 1760m 1761m 1762m 1763m 1764m 1765m 1766m 1767m 1768m 1769m 1770m 1771m 1772m 1773m 1774m 1775m 1776m 1777m 1778m 1779m 1780m 1781m 1782m 1783m 1784m 1785m 1786m 1787m 1788m 1789m 1790m 1791m 1792m 1793m 1794m 1795m 1796m 1797m 1798m 1799m 1800m 1801m 1802m 1803m 1804m 1805m 1806m 1807m 1808m 1809m 1810m 1811m 1812m 1813m 1814m 1815m 1816m 1817m 1818m 1819m 1820m 1821m 1822m 1823m 1824m 1825m 1826m 1827m 1828m 1829m 1830m 1831m 1832m 1833m 1834m 1835m 1836m 1837m 1838m 1839m 1840m 1841m 1842m 1843m 1844m 1845m 1846m 1847m 1848m 1849m 1850m 1851m 1852m 1853m 1854m 1855m 1856m 1857m 1858m 1859m 1860m 1861m 1862m 1863m 1864m 1865m 1866m 1867m 1868m 1869m 1870m 1871m 1872m 1873m 1874m 1875m 1876m 1877m 1878m 1879m 1880m 1881m 1882m 1883m 1884m 1885m 1886m 1887m 1888m 1889m 1890m 1891m 1892m 1893m 1894m 1895m 1896m 1897m 1898m 1899m 1900m 1901m 1902m 1903m 1904m 1905m 1906m 1907m 1908m 1909m 1910m 1911m 1912m 1913m 1914m 1915m 1916m 1917m 1918m 1919m 1920m 1921m 1922m 1923m 1924m 1925m 1926m 1927m 1928m 1929m 1930m 1931m 1932m 1933m 1934m 1935m 1936m 1937m 1938m 1939m 1940m 1941m 1942m 1943m 1944m 1945m 1946m 1947m 1948m 1949m 1950m 1951m 1952m 1953m 1954m 1955m 1956m 1957m 1958m 1959m 1960m 1961m 1962m 1963m 1964m 1965m 1966m 1967m 1968m 1969m 1970m 1971m 1972m 1973m 1974m 1975m 1976m 1977m 1978m 1979m 1980m 1981m 1982m 1983m 1984m 1985m 1986m 1987m 1988m 1989m 1990m 1991m 1992m 1993m 1994m 1995m 1996m 1997m 1998m 1999m 2000m 2001m 2002m 2003m 2004m 2005m 2006m 2007m 2008m 2009m 2010m 2011m 2012m 2013m 2014m 2015m 2016m 2017m 2018m 2019m 2020m 2021m 2022m 2023m 2024m 2025m 2026m 2027m 2028m 2029m 2030m 2031m 2032m 2033m 2034m 2035m 2036m 2037m 2038m 2039m 2040m 2041m 2042m 2043m 2044m 2045m 2046m 2047m 2048m 2049m 2050m 2051m 2052m 2053m 2054m 2055m 2056m 2057m 2058m 2059m 2060m 2061m 2062m 2063m 2064m 2065m 2066m 2067m 2068m 2069m 2070m 2071m 2072m 2073m 2074m 2075m 2076m 2077m 2078m 2079m 2080m 2081m 2082m 2083m 2084m 2085m 2086m 2087m 2088m 2089m 2090m 2091m 2092m 2093m 2094m 2095m 2096m 2097m 2098m 2099m 2100m 2101m 2102m 2103m 2104m 2105m 2106m 2107m 2108m 2109m 2110m 2111m 2112m 2113m 2114m 2115m 2116m 2117m 2118m 2119m 2120m 2121m 2122m 2123m 2124m 2125m 2126m 2127m 2128m 2129m 2130m 2131m 2132m 2133m 2134m 2135m 2136m 2137m 2138m 2139m 2140m 2141m 2142m 2143m 2144m 2145m 2146m 2147m 2148m 2149m 2150m 2151m 2152m 2153m 2154m 2155m 2156m 2157m 2158m 2159m 2160m 2161m 2162m 2163m 2164m 2165m 2166m 2167m 2168m 2169m 2170m 2171m 2172m 2173m 2174m 2175m 2176m 2177m 2178m 2179m 2180m 2181m 2182m 2183m 2184m 2185m 2186m 2187m 2188m 2189m 2190m 2191m 2192m 2193m 2194m 2195m 2196m 219











WARNING
DO NOT STARE AT THE SUN VISOR
WHEN DRIVING. IT MAY DISTRACT
YOU AND CAUSE AN ACCIDENT.
DO NOT TOUCH THE SUN VISOR
WHEN DRIVING. IT MAY DISTRACT
YOU AND CAUSE AN ACCIDENT.

DISEASE
PREVENTION
TREATMENT

15

 **AIR BAG WARNING**
DO NOT COVER OR REMOVE
THIS LABEL

 **WARNING**
DO NOT COVER AIR BAGS
OR REMOVE THIS LABEL

5345

**DISEASE
PREVENTION**

AIR BAG WARNING



5345





⚠ WARNING	
	<p>DEATH or SERIOUS INJURY can occur</p> <ul style="list-style-type: none">• Children 12 and under can be killed by the air bag• The BACK SEAT is the SAFEST place for children• NEVER put a rear-facing child seat in the front• Sit as far back as possible from the air bag• ALWAYS use SEAT BELTS and CHILD RESTRAINTS







NOTE













NOTE



OCUR
in the
area
of
PANTS